



UNIFIED VIDEO, ACCESS & SECURITY SYSTEMS

INTEGRITI

EliteX Release Notes
January 2026

INNERRANGE.COM

Table of Contents

INTEGRITI

Table of Contents	
Version 3.2.0	3
Version 3.1.0	4
Version 3.0.15	5
Version 3.0.14	6
Version 3.0.13	7
Version 3.0.12	8
Version 3.0.11	9
Version 3.0.4	10
Version 3.0.3	11
Version 3.0.2	12
Contact	13

Version 3.2.0**Version 3.2.0**

January 2026

New Features

- Elite X has been updated for use in CP-01 compliant systems.

Alteration

- Area Array LED mode can optionally show Area status from Area 1 instead of the terminal's Associated area.

Issues Resolved

- Resolve an issue where the keypad backlight was not turning on after first key press.
- Fix Encryption key occasionally cannot be edited after restarting EliteX terminal.

Version 3.1.0

INTEGRITI

Version 3.1.0

December 2021

New Features

- Changed the default configuration so that the beeper is controlled by AUX4.
- Added a new security mechanism to update the file. Note: Units that ship with this firmware won't be able to downgrade to an older firmware.

Alteration

- Improved detection of substitute modules on the RS485 LAN.
- Allowed LAN addresses up to 255 on Inception.

Version 3.0.15

INTEGRITI

Version 3.0.15

October 2020

Issues Resolved

- Fixed issue on Concept where exit beeper which has aux timer could turn on erroneously at end of timer if beeper was canceled by user pressing END.

New features

- Cyrillic character support (language 13) added.

Version 3.0.14

INTEGRITI

Version 3.0.14

July 2019

Issues Resolved

- Resolved an issue on concept that could prevent areas with EliteX system inputs programmed from arming correctly.
- Resolved an issue where the display could get stuck in the off state.

Version 3.0.13

INTEGRITI

Version 3.0.13

August 2018

Issues Resolved

- Fixed some issues with entering of the LAN key on Class 5 systems.
- Fixed issue where built-in SIFER reader module could become slow or unresponsive.

Version 3.0.12

INTEGRITI

Version 3.0.12

May 2018

New Features

- Added a 12 hour inverting screen saver to help minimise burn in of the OLED display
- Please note when you upgrade the firmware to this version 12 hour invert screen saver will be enabled by default. This feature can be changed in terminal configuration.

Alterations

- Brighten the keypad backlight as soon as card presence is detected
- Limit the "Min Keypad&OLED Brightness" to 20 to reduce screen burn in
- Adjusted some font characters for language 8 (Polish)
- Increased the keypad backlight turn on rate for improved utility in darkness

Issues Resolved

- Resolved an issue with LED brightness and beep volume
- Resolved issues with zone EOL configuration

Version 3.0.11

INTEGRITI

Version 3.0.11

November 2017

New Features

- After a module number collision, allow the user to change the module number without reset.

Alterations

- For EliteX with SIFER, disable the keypad while a card is present, to prevent accidental key presses.
- Change DOTL behaviour to match the Elite DOTL.

Issues Resolved

- Resolved issues with the Configuration screens.
- Resolved issues with reporting system inputs on Concept LAN.
- Resolved issues with processing the EliteX hardware inputs.
- Resolved an issue when operating on the downstream side of a fibre modem.
- Resolved issues displaying LCD messages when the default display is System Time.
- Resolved issues with timed auxiliaries when used on a Concept LAN.

Version 3.0.4

INTEGRITY

Version 3.0.4

August 2017

New Features

- Added new EliteX-only LED modes

Alterations

- Improvements to H/W Rev display on console

Issues Resolved

- Fixed timed beep in LCD commands, used for location beeper. Value of 255 now means continuous pulsing tone until stopped.
- Decreased the limit for Keypad back-light brightness on Rev A hardware to avoid flicker
- Increased the reliability of tamper detection

Version 3.0.3**Version 3.0.3**

August 2017

Alterations

- Improved the aesthetics of the system time display

Issues Resolved

- Resolved several minor display issues
- Fixed an issue when doing firmware download
- Resolved issues with the idle area display

Version 3.0.2

INTEGRITI

Version 3.0.2

July 2017

Initial Release



Global Headquarters

Inner Range **Australia**

+61 3 9780 4300
anz@innerrange.com

Inner Range **United States**

+1 (844) 588-0874
usa@innerrange.com

Inner Range **United Kingdom**

+44 (0) 845 470 5000
uk@innerrange.com

Inner Range **Canada**

+1 (905) 568-8999
canada@innerrange.com

Inner Range **Middle East**

+971 4 8067100
middleeast@innerrange.com

Inner Range **India**

+91 80 4070 3333
asia@innerrange.com

INNERRANGE.COM